














那覇港

軽石漂着 状況写真撮影位置図



注) 撮影日は、写真ページ右下へ表示

<p>①漂着なし</p>  <p>2021/12/23 11:14</p>	<p>②漂着なし</p> 	<p>③</p> 
<p>④</p> 	<p>⑤</p> 	<p>⑥漂着なし</p>  <p>2021/12/23 11:25</p>
<p>⑦</p> 	<p>⑧漂着なし</p>  <p>2021/12/23 11:24</p>	<p>⑨</p>  <p>2021/12/23 11:14</p>
<p>⑩</p>  <p>2021/12/23 11:22</p>	<p>⑪</p>  <p>2021/12/23 11:17</p>	<p>⑫</p> 

注) 少量で、写真上では確認出来ないものは、「漂着なし」と記しております。

撮影日：令和3年12月23日